# SECTION 02 20 00 - Assessment

Document revision history: 08/2019 - Original Publication

Date	Section	Description of Change

# PART 1 - GENERAL

## 1.1 Summary

- a. Utility locates shall be initiated through the Oregon Utility Notification Center via <a href="http://www.callbeforeyoudig.org/">http://www.callbeforeyoudig.org/</a> or by calling 811.
- b. Surveying and removal of contaminated soils will be coordinated and contracted through a third party by the Owner
- c. Surveying and removal of asbestos containing materials will be coordinated and contracted through a third party by the Owner.

#### 1.2 Submittals

a. Not applicable.

# 1.3 Qualifications

a. Not applicable.

#### PART 2 - PRODUCTS

#### 2.1 Materials

a. Not applicable.

# PART 3 - EXECUTION

# 3.1 Installation

a. Not applicable.

# 3.2 Interface with other products

a. Not applicable.

## 3.3 Testing

a. Not applicable.

## 3.4 Training

a. Not applicable.

# SECTION 02 41 00 - Demolition

Document revision history: 08/2019 - Original Publication

Date	Section	Description of Change

#### PART 1 - GENERAL

## 1.1 Summary

a. Refer to specific finish sections for patching requirements.

#### 1.2 Submittals

a. Submit copies of all dump fee records associated with solid waste (demolition) disposal to the Owner. Lane County requires all solid waste materials taken to a landfill to be disposed of within the Lane County, or hauler is subject to additional Lane County System Benefit Fee. These records are UOs confirmation of the dump location of materials from our projects.

# 1.3 Qualifications

a. When Cutting or Boring Concrete in any part of the sciences complex or student housing, the building manager and users must be notified by CPFM a minimum of 48hrs prior to work beginning due to the sensitive nature of activities in those areas. Contractor shall give Owner's Representative or Project Manager 24 hours' notice, prior so they are able to provide the required 48 hours' notice to users.

#### PART 2 - PRODUCTS

## 2.1 Materials

a. Materials removed during demolition process are to be separated and recycled. It is preferred that this occurs through an Eco-Sort type of process.

## PART 3 – EXECUTION

## 3.1 Installation

- a. All cutting is to be with vertical, straight-line joints.
- b. Replace surroundings to their original condition.

# 3.2 Interface with other products

- a. Prior to cutting or boring through existing materials, locate existing pipe, conduit, structure, etc.; interior and exterior.
- b. Tunnels and buried utilities must be located prior to jack-hammering, excavation, etc. If tunnel ceiling damage occurs this must be repaired to CPFM satisfaction at the contractor's expense.

## 3.3 Testing

a. Not applicable.

#### 3.4 Training

08/2019

a. Not applicable.